


KEY PLAN



ROOM NAME/SPACE

Roof

HISTORICAL OVERVIEW/SOURCES & ASSOCIATIONS

Refer Illustrated Chronology
Figures 1 and 2

The roof to the main house has retained its original form, but there has been radical alteration to the verandahs and outbuildings.



Rear view of the roof, from Courtyard 1 [Room 19]. The skylight lights Room 9. The dormer roof portion may have housed an earlier AC system.

PF photograph 1998

ROOM OR SPACE DESCRIPTION

Terra cotta tiled roof generally

COMPARATIVE SIGNIFICANCE RATING

3 : High cultural significance

COMPARATIVE CONSERVATION/WORKS STRATEGY RATING

Routine conservation maintenance *RCM*