


KEY PLAN



ROOM NAME / CURRENT & PREVIOUS NAMES

Men's WC, Toilets Room 3

HISTORICAL OVERVIEW / SOURCES & ASSOCIATIONS

Remnant of original 'Lindsay' toilet

ROOM OR SPACE DESCRIPTION

Principal Elements

Floors: Concrete

Walls generally: Plastered masonry walls

Ceiling: Not known

General trims: Not known

COMPARATIVE SIGNIFICANCE RATING

2 : Moderate cultural significance

COMPARATIVE CONSERVATION / WORKS STRATEGY RATING

CP Conservation and interpretation policy to be in alignment with this Conservation Management Plan [refer Volume 4].